

Toronto Ravine Major Maintenance



Figure 1. Eroding bank at failed TRCA erosion control asset along the main branch of the Don River, City of Toronto.

Toronto Waterfront Major Maintenance




Figure 2. Eroded headland structure in Bluffers Park, City of Toronto.

Valley Erosion Hazards



Figure 3. Slope failure at a Valley Erosion Hazard Site in the City of Toronto.

York Region Infrastructure



Figure 4. Exposed manhole chamber along Rainbow Creek Site 2.

York Region Maintenance & Other Hazards (TRCA Priorities)



Figure 5. Eroding bank and trail in Boyd Conservation Area, City of Vaughan.

Region of Peel Erosion Control & Infrastructure Protection



Figure 6. Exposed sanitary sewer (circled) at Region of Peel Infrastructure Site P-315.

Toronto Water Monitoring



Figure 7. Exposed manhole chamber along Black Creek, City of Toronto.

Recoverable Projects



Figure 8. Eroding bank and trail along Newtonbrook Creek, City of Toronto.

Yellow Creek / Vale of Avoca




Figure 9. Active construction at the Yellow Creek Emergency Works Site, City of Toronto.




Figure 10. Active construction at the Yellow Creek Emergency Works Site, City of Toronto.