

ATTACHMENT 3
SITE PHOTOGRAPHS – EXISTING CONDITIONS



Photograph 1: View of the existing concrete block retaining wall and bank scour along the west bank.



Photograph 2: View of displaced concrete blocks of the retaining wall at the location of the bank scour.