

Figure 1. Erosion near public bench at WF04.13. Source: TRCA, 2022.



Figure 2. Aerial view of scoured shore behind headland at Whimbrel Point. Source: TRCA, 2021.



Figure 3. Land view of scoured shore behind headland at Whimbrel Point. Source: TRCA, 2022.