	Dams					
Project Name	Structure	Priority	Funding Status	Potential Funding	Estimated Cost (2023 dollars)	Description
Stouffville Dam Embankment and Emergency Spillway Repair	Stouffville Dam	High	Unfunded	WECI/ICIP	\$505,000	 Embankment requires rip rap buttressing on downstream slope to increase factor of safety. Emergency spillway requires erosion protection.
Palgrave Dam Major Maintenance and Overtopping Protection	Palgrave Dam	High	Unfunded	WECI/ICP/DMAF	\$1,125,000	 Dam requires repairs to install overtopping protection on the embankment. Stop log deck and hoisting system require upgrades to allow installation and removal of stop logs.
Glen Haffy Extension Dams Decommissioning	Glen Haffy Extension Upper Dam and Lower Dam	High	Partially Funded	WECI/ICIP/DMAF	\$1,687,000	 Engineering study for decommissioning approvals. Implementation of decommissioning.
Stouffville Dam Embankment Repair	Stouffville Dam	Medium	Unfunded	WECI/ICIP/DMAF	\$281,000	 Emergency spillway requires erosion protection. Earthen embankment does not meet factor of safety requirements.
Stouffville Channel Major Maintenance and Naturalization	Stouffville Dam	High	Unfunded	ICIP/DMAF	\$1,012,000	 Removal of existing gabion basket lining and replace with natural channel materials.
Pickering/Ajax Dyke Reconstruction	Pickering Dyke/Ajax Dyke	High	Unfunded	ICIP/DMAF	\$14,175,000	Reconstruct dykes to meet current engineering guidelines.
Black Creek Dam Spillway Pipe Modification	Black Creek Dam	Medium	Unfunded	WECI/ICIP/DMAF	\$1,125,000	Modify spillway pipe to eliminate debris blockages.
G. Ross Lord Dam Gate Optimization and Operational Study	G. Ross Lord Dam	Medium	Partially funded	WECI/ICIP/DMAF	\$393,000	• Engineering study to maximize G. Ross Lord Dam's reservoir storage for short duration, high intensity storms.
Secord Dam Decommissioning	Secord Dam	Medium	Unfunded	ICIP/DMAF	\$1,237,000	Engineering studies and dam decommissioning works.
Osler Dam Decommissioning	Osler Dam	High	Unfunded	ICIP/DMAF	\$337,000	Engineering studies and dam decommissioning works.
Woodbridge Grade Control Structure Removal (Board of Trade Weirs)	Woodbridge Channel	Low	Unfunded	ICIP/DMAF	\$1,125,000	Engineering study and removal of two grade control weirs.
G. Ross Lord Dam Safety Review	G. Ross Lord Dam	Low	Funded	WECI	\$191,000	Undertake Dam Safety Review
Claireville Dam Major Maintenance	Claireville Dam	Low	Unfunded	WECI/ICIP/DMAF	\$7,875,000	 Enlarge spillway apron for extreme flows. Upgrade gate hoisting systems and repaint gates. Repair spillway wall.
Milne Dam Major Maintenance	Milne Dam	Medium	Unfunded	WECI/ICIP/DMAF	\$3,037,000	 Install overtopping protection to earthen embankment. Enlarge spillway apron for extreme flows. Increase factor of safety for spillway and wing walls.
Total					\$34,105,000	