



**Figure 1.** View of tableland conditions facing west; the erosion scour (surrounded by orange safety fencing) has grown in size since the initial inspection.



**Figure 2.** Slope crest with view of bare and unvegetated erosion scour on the slope crest facing east towards the Main Street South roadway.