


## Attachment 2 – Site Photos



The above plan shows the approximate location and direction of photos from **Figure 1** and **Figure 2**, below. Dashed red boxes represent area of photo shown in aerial photographs from **Figure 3** and **Figure 4**, below.





**Figure 1.** A bank scour and meander cut off is threatening the Leslie Collector sewer at German Mills Settlers Park Sanitary Protection Project Site 2-3. *Source: TRCA, 2020.*



**Figure 2.** The Leslie Collector main and maintenance hole is at risk of erosion downstream of the pedestrian bridge in German Mills Settlers Park. *Source: TRCA, 2018.*





**Figure 3.** Aerial photo of the north end of project area where the Leslie Collector sewer is at risk from erosion. *Source: TRCA, 2021.*



**Figure 4.** Aerial photo of the south end of project area where the Leslie Collector sewer, pedestrian bridge and trail are at risk of erosion. *Source: TRCA, 2021.*