

Attachment 2 – Hudson Drive Photos - Toronto,



Figure 1. View of the slope failure from the Beltline Trail facing southwest towards 193 – 195 Hudson Drive. Red dashed line highlighting slope failure. *Source: TRCA 2018*



Figure 2. Drone photography of the slope failure facing southeast below 193 – 195 Hudson Drive. Red arrows highlighting 193 – 195 Hudson Drive. Trail to the left of the photo is the Beltline Trail. *Source: TRCA 2018*