

## Item 8.1.

### Attachment 1 – Proposed 2019 Geotechnical Investigation Sites

Section	Site	Properties Proposed for Geotechnical Investigation	Number of Properties	Site Details
1	1	220 Bartley Drive	1	<i>This site will no longer be awarded in this contract as geotechnical investigation will be completed as part of another Request for Proposal to expedite this site.</i>
	2	5-7, 16 Parkview Avenue, 472 Wellesley Street East and Wellesley Park	5	Homeowners notified TRCA of erosion issues following the severe rainfall event in May 2017.
	3	525-555 Donlands Avenue	16	The site was flagged to TRCA by homeowners after the July 8, 2013 severe weather event and through desktop review.
	4	2-6 Moorehill Drive and 30-36 Bennington Heights Drive	7	The properties along Moorehill Drive and Bennington Heights Drive were flagged by desktop review.
	5	Burke Brooke	3	The properties within Burke Brooke were flagged by desktop review.
	6	36 Glengrove Avenue East	1	This site was identified during a site visit by TRCA staff in Spring 2019.
	7	20-38 Restwell Crescent, 6-8 Courtwood Place and 15-21 Viamede Crescent	14	The site was flagged to TRCA by City of Toronto staff and through desktop review.
2	8	94-224 Parkview Hill Crescent and 1-5 Welby Circle	65	Erosion concerns at 96 and 98 Parkview Hill Crescent were identified to TRCA during Spring 2019. Due to the proximity of the slope to the private properties, TRCA extended the study area to encompass majority of the northern section of Parkview Hill Crescent and Welby Circle.
3	9	32-34 Hertford Avenue	2	Homeowners notified TRCA of erosion issues in 2016.
	10	108-110 Culford Road	2	The site was flagged to TRCA by City of Toronto staff.
	11	21 Sunnybrae Crescent	1	The property was flagged by desktop review.
	12	26 Kennerly Court	1	The property was flagged by desktop review.
	13	144 Stilecroft Drive	1	The property was flagged by desktop review.

## Item 8.1.

4	1	2-50 Meadowcliffe Drive	11	While previous geotechnical assessments have been completed for this site, TRCA constructed a shoreline structure and an updated SS&ERA is recommended
	2	767 Royal York Road	1	Previous SS&ERAs were completed between 2014 and 2015 for these sites, however an updated Long-Term Stable Slope Crest (LTSSC) with Factor of Safety of 1.3 is recommended.
	3	323 Riverview Drive	1	
	4	10 Burnhamthorpe Crescent	1	
	5	12 King George's Drive	1	
	6	49 Collingdale Road	1	
	7	161-167 Grandravine Drive	4	<i>This site will no longer be awarded in this contract as geotechnical investigation will be completed part of another Request for Proposal to expedite this site.</i>
	8	4-8 Earldown Drive	3	Previous SS&ERAs were completed between 2014 and 2015 for these sites, however an updated Long-Term Stable Slope Crest (LTSSC) with Factor of Safety of 1.3 is recommended.
	9	66-70 Celeste Drive	3	
	10	108 Hardian Drive	1	
	11	75 Strathavon Drive	1	
	12	21-23 Hackmore Avenue	2	
	13	87 & 101 Bankview Circle	2	
	14	5-61 Moon Valley Drive	21	
	15	24-36 Watercliffe Drive	7	
	16	28-30, 62-64 Topbank Drive	4	
	17	4 Hardwood Gate	1	
	18	32-40 Esther Lorrie Drive	4	
	19	100 North Drive	1	
	20	17 Treeline Court	1	
	21	30 Grovetree Road	1	